



Feature importance for full parameter range


ECA




ThickA




ECB



ThickB



ECC



HCP_1.0_0.1	HCP_2.5_0.3	HCP_4.0_0.5	VCP_2.5_0.1	VCP_4.0_0.3	PRP_1.0_0.5	PRP_4.0_0.1
HCP_1.0_0.3	HCP_2.5_0.5	VCP_1.0_0.1	VCP_2.5_0.3	VCP_4.0_0.5	PRP_2.5_0.1	PRP_4.0_0.3
HCP_1.0_0.5	HCP_4.0_0.1	VCP_1.0_0.3	VCP_2.5_0.5	PRP_1.0_0.1	PRP_2.5_0.3	PRP_4.0_0.5
HCP_2.5_0.1	HCP_4.0_0.3	VCP_1.0_0.5	VCP_4.0_0.1	PRP_1.0_0.3	PRP_2.5_0.5	others